

Invaluable when the power source cannot be situated directly beside the welder, remote controls can help improve productivity and reduce welder fatigue.

Product compatibility

GYSARC 300 TRI
GYSARC 400 TRI
PROGYS 220E FV
PROGYS FLEX 280 CEL
EXAGON 400 CC/CV
EXAGON 400 FLEX CC/CV
PROTIG 221 DC FV
PROTIG 231 DC FV
PROTIG 231L DC FV
TITAN 231 DC FV
TIG 300 DC
TITAN 400 DC TRI
PROTIG 201 AC/DC FV
PROTIG 201L AC/DC
TITANIUM 230 AC/DC FV
TIG 250 AC/DC
TITANIUM 400 AC/DC TRI



Compatible processes

MMA / TIG

How it works

The remote control can be used to regulate the current between 50% and 100% of the current value set on the welding machine.

Example:

The current on the product is set to 120A. With the remote control, the current can be adjusted between 60A and 120A.

Cable length

8 m or 20 m

Accessories (optional extras)

7-pin male connector

045699



8 m (045675)
20 m (066625)

7 pins